

WELL LOG AND DRILLING REPORT

ORIGINAL

77

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 140430

1362 W. First Ave 12
County Washington LOCATED Waterford Section of Township
Owner Richard Buck Address Beverly
Location of property 1/2 mi E of Beverly on Rt 77

CONSTRUCTION DETAILS

Casing diameter 4 7/8 Length of casing 63
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....

PUMPING TEST

Pumping rate.....G.P.M. Duration of test.....hrs.
Drawdown.....ft. Date.....
Developed capacity
Static level—depth to water.....ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>7' Soil & Loam</u>	<u>0 Feet</u>	<u>15 Ft.</u>
<u>Sand & Gravel</u>	<u>15</u>	<u>63</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

S.

See reverse side for instructions

Drilling Firm Burfield & Son

Address Stockport B

Date 8/24 - 56

Signed Burfield