

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

No 164137

County Malheur Township Jackson ? Section of Township
or Lot Number

Owner Mrs. Lema Harris Address Warren Ohio RD #2

Location of property South side of Bitchard Chilton 1/4 mile west of the Ellsworth Bailey Road

CONSTRUCTION DETAILS

Casing diameter 5 7/8 Length of casing 1'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

PUMPING TEST

Pumping rate 3 G.P.M. Duration of test 1/2 hrs.

Drawdown 3 ft. Date March 21 1957

Developed capacity 3

Static level—depth to water 6 ft.


Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	3 Ft.
sandstone	3	45
Shale	45	50
Water - 35		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Don Culora Co

Address MC 53 Warren Ohio

Date March 21 1957

Signed Don Culora

3
LOCATED