

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 181787

County Gallia Township Huntington Section of Township 27
Owner Willard Woodruff Address Vinton - R D
Location of property Mount Tabor Rd - 4th house on left
MT TABOR RD

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST	
Casing diameter <u>5 1/8</u>	Length of casing <u>115'</u>	Pumping rate..... G.P.M.	Duration of test..... hrs.
Type of screen.....	Length of screen.....	Drawdown..... ft.	Date.....
Type of pump.....		Developed capacity.....	
Capacity of pump.....		Static level—depth to water <u>76'</u>	ft.
Depth of pump setting.....		Pump installed by.....	
Date of completion.....			

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>Yellow clay</u>	<u>0 Feet</u>	<u>17 Ft.</u>	
<u>Blue Clay</u>	<u>17</u>	<u>41</u>	
<u>Sandstone</u>	<u>41</u>	<u>45</u>	
<u>Blue Slate</u>	<u>45</u>	<u>65</u>	
<u>Sandstone</u>	<u>65</u>	<u>70</u>	
<u>Blue Shale</u>	<u>70</u>	<u>75</u>	
<u>Gray shale</u>	<u>75</u>	<u>105</u>	
<u>Sandstone</u>	<u>105</u>	<u>120</u>	

S.
See reverse side for instructions

Drilling Firm Ray Stone
Address Langsville

Date Sept 20 - 1960
Signed Ray Stone 22