

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 210166

County Greene Township Bath Section of Township 3
Owner L. E. Kink Address 5689 Valley Pike, Dayton, Ohio
Location of property 5689 Valley Pike, Dayton, Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST


Casing diameter 5 5/8" Length of casing none Pumping rate..... G.P.M. Duration of test..... hrs.
Type of screen..... Length of screen..... Drawdown..... ft. Date 12/15/59
Type of pump..... Developed capacity.....
Capacity of pump..... Static level—depth to water..... ft.
Depth of pump setting..... Pump installed by.....
Date of completion.....

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
#1. Clay.	0 Feet	10 Ft.
Clay	10	16
dry gravel	16	20
Shale	20	34
#2. Mud	0	10'
S. Mud	10	17
dry gravel	17'	17 1/2
Shale	17 1/2	22

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Don Roe
Address Vandalia, Ohio

Date 12/15/59
Signed Don Roe

(15) (16)