

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 223544

County Fairfield Township Amanda Section of Township 29
Owner P. Hartman Address Amanda Hl
Location of property 2 mi S. of Cedar Hill on Co. rd. Cedar Hill Rd.
Cedar Hill

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 12
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting 100
Date of completion.....

BAILING OR PUMPING TEST


Pumping rate..... G.P.M. Duration of test 1 1/2 hrs.
Drawdown None ft. Date May 4 - 64
Developed capacity.....
Static level—depth to water 60 ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	 Ft.
<u>yellow clay</u>	<u>5-0</u>	<u>5-0</u>
<u>Soft sand rock</u>	<u>7-0</u>	<u>12-0</u>
<u>yellow "</u>	<u>63-0</u>	<u>75-0</u>
<u>gray " "</u>	<u>60-0</u>	<u>135-0</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Shamus
Address Amanda

Date 1964
Signed Ben Kershner

70
LOCATED
70