

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 234564

County Pickaway Township Circleville Section of Township
 Owner Ralph H. Dresbach Address Circleville, Ohio
 Location of property Sturm & DILLARD ~~Prop~~ property on Island Rd.
Wall on EAST SIDE of ROAD

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4" Length of casing
 Type of screen Length of screen
 Type of pump
 Capacity of pump
 Depth of pump setting
 Date of completion


Pumping rate 6 G.P.M. Duration of test 2 hrs.
 Drawdown 5 ft. Date Aug. 25, 1960
 Developed capacity
 Static level—depth to water 15 ft.
 Pump installed by

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>clay</u>	<u>0 Feet</u>	<u>4 Ft.</u>
<u>fine sand</u>	<u>4</u>	<u>7</u>
<u>blue brick</u>	<u>7</u>	<u>37</u>
<u>fine sand</u>	<u>37</u>	<u>43</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Harley Dagg
 Address 546 E. 1st St. Main St.

Date Sept. 21, 1960
 Signed