

WELL LOG AND DRILLING REPORT


ORIGINAL

State of Ohio
 DEPARTMENT OF NATURAL RESOURCES
 Division of Water
 1562 W. First Avenue
 Columbus, Ohio

No. 258895

County Clermont Township Miami Section of Township _____
 Owner Village of Milford Address Milford Ohio
 Location of property Milford Water Works Water SE.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>16"</u> Length of casing <u>58'</u>	Pumping rate <u>500</u> G.P.M. Duration of test <u>24</u> hrs.
Type of screen <u>BRONZE</u> Length of screen <u>10'</u>	Drawdown <u>5 1/2</u> ft. Date <u>4/14/64</u>
Type of pump _____	Developed capacity <u>784 G.P.M.</u>
Capacity of pump _____	Static level—depth to water <u>18</u> ft.
Depth of pump setting _____	Pump installed by _____
Date of completion <u>4/18/64</u>	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc. 
<u>SAND - GRAVEL</u>	0 Feet	<u>58</u> Ft.	

S.
 See reverse side for instructions