

# WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL  
OR TYPEWRITER  
DO NOT USE INK.

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
1562 W. First Avenue  
Columbus 12, Ohio

AK-See Quad 37  
No 278897

County Washington Township Warren Section of Township Sec 26

Owner Mrs. McVay Address Manilla D. Route 4

Location of property Township Road 282 (State Rt 7) Constitution  
County Rd 3 to Township Rd 283 north one mile to 282

## CONSTRUCTION DETAILS

Casing diameter 5 5/8 Galv Length of casing 42' 2"  
Type of screen..... Length of screen.....  
Type of pump.....  
Capacity of pump.....  
Depth of pump setting.....  
Date of completion.....

## BAILING OR PUMPING TEST

Pumping Rate 50 G.P.M. Duration of test 12 hrs.  
Drawdown 15 ft. Date 3-27-64  
Static level-depth to water 37 ft.  
Quality (clear, cloudy, taste, odor) clean  
Pump installed by.....


## WELL LOG

| Formations<br>Sandstone, shale, limestone,<br>gravel and clay | From          | To            |
|---------------------------------------------------------------|---------------|---------------|
| <u>Red Mud</u>                                                | <u>0 Feet</u> | <u>34 Ft.</u> |
| <u>sand</u>                                                   | <u>34</u>     | <u>44</u>     |
| <u>Red Rock</u>                                               | <u>44</u>     | <u>50</u>     |
| <u>slate</u>                                                  | <u>50</u>     | <u>55</u>     |
| <u>Red Rock</u>                                               | <u>55</u>     | <u>62</u>     |

Water at 37 ft  
Gravel packed  
Unmatted

## SKETCH SHOWING LOCATION

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.



S.  
See reverse side for instructions

Drilling Firm Jaybird Hadden  
Address Route 4 Manilla D

Date 3-30-64  
Signed C Hadden

39