

# WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL  
OR TYPEWRITER  
DO NOT USE INK.

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
1562 W. First Avenue  
Columbus 12, Ohio

No 287159

County Madison Township Pleasant Section of Township \_\_\_\_\_  
Owner Marvin Fulton Address Rt 1, Mt Sterling, O  
Location of property S.W. End of Mt Sterling on Rt 3

## CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 102  
Type of screen - Length of screen -  
Type of pump \_\_\_\_\_  
Capacity of pump \_\_\_\_\_  
Depth of pump setting \_\_\_\_\_  
Date of completion 9-12-63

## BAILING OR PUMPING TEST

Bailed 10 G.P.M. Duration of test \_\_\_\_\_ hrs.  
Pumping Rate \_\_\_\_\_  
Drawdown none ft. Date \_\_\_\_\_  
Static level-depth to water 70 ft.  
Quality (clear, cloudy, taste, odor) \_\_\_\_\_  
Pump installed by \_\_\_\_\_

## WELL LOG

| Formations<br>Sandstone, shale, limestone,<br>gravel and clay | From   | To     |
|---------------------------------------------------------------|--------|--------|
| Clay                                                          | 0 Feet | 20 Ft. |
| Sand + gravel                                                 | 20     | 40     |
| Blue Clay                                                     | 40     | 74     |
| Red Clay                                                      | 74     | 90     |
| Sand                                                          | 90     | 96     |
| Blue Clay                                                     | 96     | 102    |
| lime Stone                                                    | 102    | 110    |
| water                                                         |        |        |

## SKETCH SHOWING LOCATION

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.

Cemetery Mt. N.  
1 1/2 mi. N.E.  
Mt Sterling, O  
Rt 3  
Rt 56  
well & E.  
Fulton-Property