

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 393503

County Washington Township Muskegon Section of Township NE. Cor. Sec 8

Owner Raymond Mahoney Address Route 2 Manetta O.

Location of property County Rd 41 + ~~County Rd 79~~

CONSTRUCTION DETAILS

Casing diameter 6" plastic Length of casing 45'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 1.5 G.P.M. Duration of test 4 hrs.
Drawdown 3 ft. Date 3-24-69
Static level-depth to water 15 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by owner

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>top soil</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>Red Mud</u>	<u>2</u>	<u>10</u>
<u>Sandstone</u>	<u>10</u>	<u>15</u>
<u>Red shale</u>	<u>15</u>	<u>23</u>
<u>lime shell</u>	<u>23</u>	<u>25</u>
<u>Red shale</u>	<u>25</u>	<u>32</u>
<u>Sandstone</u>	<u>32</u>	<u>35</u>
<u>Red shale</u>	<u>35</u>	<u>43</u>
<u>lime</u>	<u>43</u>	<u>45</u>
<u>to depth 45</u>		
<u>Gravel packed</u>		
<u>Cemented</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Halden's

Date 3-24-69

Address 114 Sheridan St
Manetta Ohio

Signed C. Halden

*If additional space is needed to complete well log, use next consecutive numbered form.