

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 393955

County LUCAS Township SYLVANIA Section of Township 27

Owner CADILLAC ESTATES HOMES Address 2322 MANOA ST

Location of property LAST HOUSE ONEAST SIDE OF MANOA ST. NORTH OF BANCROFT

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST (Specify one by circling)	
Casing diameter <u>4 1/4</u> Length of casing <u>67'</u>			Test Rate <u>3</u> G.P.M. Duration of test <u>2</u> hrs.	
Type of screen <u>NONE</u> Length of screen _____			Drawdown <u>26'</u> ft. Date <u>JUNE 5 1971</u>	
Type of pump <u>1/3 HP. REDA</u>			Static level-depth to water <u>64'</u> ft.	
Capacity of pump <u>10 GPM.</u>			Quality (clear, cloudy, taste, odor) <u>CLEAR</u>	
Depth of pump setting <u>90'</u>			Pump installed by <u>BOB LARSON WELL DRILLING</u>	
Date of completion <u>JUNE 9 - 1971</u>				
WELL LOG*			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>YELLOW SAND</u>	0 Feet	10' Ft.	N. CENTRAL W. MANOA BANCROFT E. S.	
<u>SOFT-BLUE-CLAY</u>	10'	40'		
<u>HARD PAN</u>	40'	50		
<u>SOFT BLUE CLAY</u>	50'	62		
<u>DRAB LIME-BROKEN</u>	62	66		
<u>DRAB BLUE-LIME</u>				
<u>HARD</u>	66	78		
<u>BLUE LIME-SOFT</u>	78	94'		

Drilling Firm BOB LARSON WELL-DRILLING

Date JUNE 10, 1971

Address 4038 ALBON RD. MONCLOVA OHIO

Signed Bob Larson

329

*If additional space is needed to complete well log, use next consecutive numbered form.