

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

445909

County Geauga Township Hambden Section of Township _____
Owner Wm Janin Address 12972 Chardon-Windoso Rd
Location of property 1 mi E of Chardon on N Side

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 5/8 Length of casing 32
Type of screen _____ Length of screen _____
Type of pump Red Jacket Sub
Capacity of pump 43 H
Depth of pump setting 50'
Date of completion 11/20/72


Test Rate 10 G.P.M. Duration of test 1 hrs
Drawdown 10 ft. Date 11/20/72
Static level-depth to water 35 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by Hendershot

WELL LOG*

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow clay</u>	<u>0 Feet</u>	<u>15 Ft.</u>
<u>Hard pan</u>	<u>15</u>	<u>32</u>
<u>yellow S.S.</u>	<u>32</u>	<u>55</u>
<u>Blue shale</u>	<u>55</u>	<u>65</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm _____
Address RD 1 Box 60 Chardon A

Date 11/20/72
Signed W. C. Hendershot 77

*If additional space is needed to complete well log, use next consecutive numbered form.