

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

505551

COUNTY Huron TOWNSHIP New Haven SECTION OF TOWNSHIP Sect 3
OWNER Midwest Industries ADDRESS Conwell Ave Willard 044890
LOCATION OF PROPERTY At Intersection of 99 & 224 on RT 99 E side
Approx. 100'

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 8" Length of casing 107 1/2'
Type of screen Coat Slot Length of screen 8'
Type of pump Sub.
Capacity of pump 220 gpm @ 81' pressure
Depth of pump setting 103'
Date of completion 11-20-76
Test rate 250 gpm Duration of test 6 hrs
Drawdown 13 ft Date 11-21-76
Static level (depth to water) 49' 10" ft
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Driller

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Yellow Clay	0 ft	19 ft
Blue	19	54
Quick Sand	54	63
Blue Clay	63	92
Water Sand	92	111

This well Replace old
5 1/2" Well Which Screen
Ate out & filled up with
Sand.

W

N

RT 99
Conwell Ave

x Midwest Ind.

RR Dannelly

E

RT 224

S

DRILLING FIRM Myrl R. Fife DATE 11-27-76
ADDRESS RDI Greenwald 044537 SIGNED Myrl R. Fife

*If additional space is needed to complete well log, use next consecutive numbered form.