# WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 420593

County Hardin Township McDonald Section of Township

Owner Arlen Senkart Address Bellbrook, Ohio R.R.

Location of property

## CONSTRUCTION DETAILS

Casing diameter 4¼" Length of casing 156'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion Oct. 20 - 1972

## BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 600 G.P.H. ~~G.P.M.~~ Duration of test hrs.

Drawdown 3 ft. ft. Date Oct 20 - 1972

Static level-depth to water 41 ft. ft.

Quality (clear, cloudy, taste, odor)

Pump installed by

## WELL LOG*

| Formations Sandstone, shale, limestone, gravel and clay | From | To |
|---|---|---|
| Gravely Clay | 0 Feet | 35 Ft. |
| Blue Clay | 35 | 85 |
| Gravely Clay | 85 | 117 |
| Sand + Gravel | 117 | 152 |
| Gravel | 152 | 156 |

## SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.




Drilling Firm Herschel Tracy Sr. Date Oct. 20 - 1972

Address R.R. 1 Lakeview Ohio 43331 Signed Herschel Tracy Sr.

*If additional space is needed to complete well log, use next consecutive numbered form.