

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 202323

County Lucas Township Holland Section of Township _____
Owner Colman Atkins Address 8780 Howard Springs
Location of property North side of Howard Springs rd. west of Howard Rd. 800

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 5/8 Length of casing 18'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Pumping rate 12 G.P.M. Duration of test 1/2 hrs.
Drawdown 45 ft. Date Jan 20 1959
Developed capacity 12
Static level—depth to water 16 ft.
Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

Ft.

clay

14

shale

14'

38

limestone

38

42

shale

42

76

Water 38'-65'

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Howard Rd.

W.

800

E.

Howard Springs rd.

S.

See reverse side for instructions

Drilling Firm

Don Culver Co

Address

4444 Mahoning Ave
Warren Ohio

Date

Jan 20 1959

Signed

Don Culver