

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

605592

COUNTY Sandusky TOWNSHIP Ballville SECTION OF TOWNSHIP _____
OWNER Paul M. Lyet ADDRESS 3913 Tiffin Rd. Fremont, O.
LOCATION OF PROPERTY 1/4 mi. east of old Tiffin Rd. on CR 181

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter <u>5"</u> Length of casing <u>77 ft.</u>	Test rate <u>12</u> gpm Duration of test <u>3 1/2</u> hrs
Type of screen _____ Length of screen _____	Drawdown <u>32</u> ft Date <u>10-24-81</u>
Type of pump _____	Static level (depth to water) <u>28</u> ft
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>slightly cloudy</u>
Depth of pump setting _____	Pump installed by _____
Date of completion _____	

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale, limestone, gravel, clay	From	To	Locate in reference to numbered state highways, street intersections, county roads, etc.
<u>sand</u>	0 ft	18 ft	N old Tiffin Rd. CR 181 WELL CR 173 SENECA - SAND Co LINE S W E
<u>sand + clay</u>	18	56	
<u>clay</u>	56	68	
<u>broken limestone</u>	68	73	
<u>limestone</u>	73	91	

DRILLING FIRM Amel Greenwell Drilling DATE Oct 26, 1981
ADDRESS Nevada, Ohio SIGNED Paul F. Hotte

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224