

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

DEPARTMENT OF NATURAL RESOURCES

Division of Water

Columbus, Ohio

No 90108

LOCATED

823,300

82,000 N

County

Ottawa

Township

Salem

Section of Township

or Lot Number

Owner

O. M. Biens

Address

Oak Harbor O.

Location of property

Rt 19 North of Oak Harbor 1 mile.

CONSTRUCTION DETAILS

Casing diameter $1\frac{1}{4}$ Length of casing 60

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

PUMPING TEST

Pumping rate G.P.M. Duration of test hrs.

Drawdown ft. Date

Developed capacity

Static level—depth to water 10 ft. ft.

Pump installed by

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

55 Ft.

55


78

Clay Loam
LimeLocate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.



S.

See reverse side for instructions

Drilling Firm

M. O. Manahan Sons

Date

June 12, 1952

Address

Oak Harbor O.

Signed

R. A. Manahan