

WELL LOG AND DRILLING REPORT

ORIGINAL

2134 000

LOCATED

5

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 125205

County Holmes Township North Section of Township 1 or Lot Number 1
Owner Joe Anderson Address Killbuck, Ohio R. 1
Location of property 6 miles N.W. of Killbuck

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 32' 3"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____

PUMPING TEST

Build Test
Pumping rate 10 G.P.M. Duration of test 2 hrs.
Drawdown None ft. Date Nov. 11-54
Developed capacity Build down
Static level—depth to water 58 ft.
Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Drift</u>	<u>0 Feet</u>	<u>32 Ft.</u>
<u>Sand</u>	<u>32'</u>	<u>35'</u>
<u>Shale</u>	<u>35'</u>	<u>50'</u>
<u>Gray Lime</u>	<u>50'</u>	<u>55'</u>
<u>Shale</u>	<u>55'</u>	<u>77'</u>
<u>White Sand</u>	<u>77'</u>	<u>98'</u>
<u>Little water at 52'</u>		
<u>Water at 90' to 98'</u>		

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

S.

See reverse side for instructions

Drilling Firm Mrs. Claude Hill
Address Killbuck, Ohio

Date Nov. 12, 1954
Signed Mrs. F. Hill

15