

ORIGINAL
TULLO R
GROUP W

No. 382160

County Franklin Township Washington Section of Township South East
Owner Joseph W. Rydola Address 5541 Tuttle Rd
Location of property Between Kings Rd - Hayden Run

BAILING OR PUMPING TEST
(Specify one by circling)

Casing diameter 4 1/4 Length of casing 66
Type of screen non Length of screen.....
Type of pump 1 1/2 Gump
Capacity of pump 4 1/2 PPM
Depth of pump setting 24 ft
Date of completion 10 - 26 - 68

Test Rate 20 G.P.M. Duration of test 2 hrs.
Drawdown Iron ft. Date 10-6-68
Static level-depth to water 11 ft.
Quality (clear) cloudy, taste, odor) Clear
Pump installed by Everett Station

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet | 22 Ft.

22 | 31

31 | 51

51	44
----	----

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Ringed Red

Lullie Red

和

W.

E.

Haydon Ben

S.

Drilling Firm Everett Sleeth
Address 2445 Middleton Rd.

Date 4-18-69
Signed Frank H. Stakelton

*If additional space is needed to complete well log, use next consecutive numbered form.