



WELL LOG AND DRILLING REPORT

13

NO. 52456

County Seneca Township Seneca Section of Township _____
Owner Earl Risner Address Berwick O
Location of property Berwick on 587

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 Length of casing 77 Pumping rate _____ G.P.M.
Type of screen _____ Length of screen _____ Duration of test _____ hrs.
Type of pump _____ Drawdown _____ ft. Date _____
Capacity of pump _____ Developed capacity _____
Depth of pump setting _____ Static level - depth to water 45 ft.
Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation

From

To

N.

yel clay

0

20

bl. clay

50

quicksand

65

s + g.

76

gravel

77

ls.

102

W.

E.

S.

Drilling Firm FlanaganDate 3-15-60

Address _____

Copied by RS