

3.25
welded
X=1929500
Y=164000 ± 500
N

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

W15
Nº 102682

County Licking Township Jersey Section of Township or Lot Number
Owner Kenneth Williamson Address Jakobstown, O. R.F.D. 1
Location of property Beech Road, 1/2 mile South U.S. 62

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing
Type of screen Length of screen
Type of pump Hand
Capacity of pump
Depth of pump setting 75 ft.

PUMPING TEST

Pumping rate 6 G.P.M. Duration of test 1 hrs.
Drawdown 50 ft. Date Oct 20, 1954
Developed capacity 300 G.P.H.
Static level—depth to water 20 ft.
Pump installed by Owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	8 Ft.
Yellow Clay		
Blue Clay	8	18
Clay stone	18	28
Blue Clay	28	80
dry sand	80	82
Blue Clay	82	95
dry gravel	95	99
Blue Clay	99	110
dry gravel	110	112
Blue Clay	112	121
Yellow Shale	121	123
gravel, water.	123	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
Licking Co.
Franklin County
U.S. 62
W. E.
1143
123+
1020-
1/2 mile.
Beech Road
S.
See reverse side for instructions

Drilling Firm J.B. Limbula

Address Jakobstown, O.

Date Oct 20, 1954

Signed J.B. Limbula

LOCATED

15