

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

No 109628

X = 2,471,300

Y = 520,900 N
(2000 x 2000)

County Mahoning Township Austintown Section of Township or Lot Number _____
Owner Mr Gordon Minch Address South Turner Rd.
Location of property South of Rt 18 approx 1/4 on South Turner Rd.

CONSTRUCTION DETAILS

Casing diameter 6 1/4 Length of casing 16 1/2
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____

PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Developed capacity _____
Static level—depth to water 8 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Drift</u>	<u>0 Feet</u>	<u>3 Ft.</u>
<u>yellow sandstone</u>	<u>3</u>	<u>42</u>
<u>fine clay</u>	<u>42</u>	<u>44</u>
<u>sandy shale</u>	<u>44</u>	<u>65</u>
<u>gray sandstone</u>	<u>65</u>	<u>85</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S. ELEV. OF ROCK: 1080

See reverse side for instructions

Drilling Firm Robert Stevenson
Address 131 Cent St
Stark

Date 1/16/54
Signed Robert Stevenson

