

WELL LOG AND DRILLING REPORT

ORIGINAL

X = 1,501,100
(500x500)

Y = 669,700-5

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

76 ✓
No 109803

County Montgomery Township Madison Section of Township #2
Owner Asbury Earline Address 866 N. Euclid
Location of property on Ardington road

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 12 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____

PUMPING TEST


Pumping rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 3 ft. Date March 24-53
Developed capacity 10 gal per min
Static level—depth to water 23 ft.
Pump installed by [Signature]

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	2 Ft.
Clay		
lime	3	18
shale	18	57
water at 30 ft		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.

See reverse side for instructions

Drilling Firm J. J. Albers
Address 2053 S. [unclear]

Date April 17-53
Signed [Signature]

4068