

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

I₁₂
Nº 112750

County Mont Township Randolph Section of Township or Lot Number _____
Owner Robert L. Becker Address 7616 N. Main St. Dayton, Ohio
Location of property see below

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 6" O.D. Length of casing 27' 8"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Pumping rate 3 1/2 G.P.M. Duration of test _____ hrs.
Drawdown 0 ft. Date _____
Developed capacity _____
Static level—depth to water 1.8 ft.
Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top Soil</u>	<u>0 Feet</u>	<u>2</u> Ft.
<u>Clay</u>	<u>2</u>	<u>26</u>
<u>Shale w/ layers of lime stone</u>	<u>26</u>	<u>76</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

W. West Brook Rd

North Main St

S.

See reverse side for instructions

water at 56'

4071

6 200 30 30

Drilling Firm Curtis C. Conway
Address 7944 Harrington Ave
Dayton Ohio

Date Dec 19, 1956
Signed Curtis C. Conway

I 221