

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

N^o 113824

County Trumbull Township Liberty Section of Township east or Lot Number section
Owner Samuel Conlin Address 538 E. Broadway
Location of property 538 E. Broadway, Girard, Ohio

CONSTRUCTION DETAILS

Casing diameter 6 5/8" Length of casing 24'
Type of screen — Length of screen —
Type of pump minijets (Pamco)
Capacity of pump — should be
Depth of pump setting 50ft

PUMPING TEST


Pumping rate 30 G.P.M. Duration of test 1 hrs.
Drawdown 8 ft. Date July 21, 1954
Developed capacity 1,800 D.P.H.
Static level—depth to water 8 ft.
Pump installed by owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>blue clay</u>	<u>10ft.</u>	<u>20ft.</u>
<u>soft shale</u>	<u>20ft.</u>	<u>24ft.</u>
<u>gray shale rock</u>	<u>24ft.</u>	<u>60ft.</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm V. Rose Reed Driller & Ohio Date July 22, 1954
Address Western Reserve Rd. P.O. Box 1000 Signed H. H. Dooking
Ohio