

WELL LOG AND DRILLING REPORT

ORIGINAL

89-12

No 119527

LOCATED

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

County Muskingum Township Wayne Section of Township
Owner M. C. E. Marmont Address Diets Lane Jamesville, O.
Location of property Diets Lane Jamesville Ohio

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 43'-10"
Type of screen _____ Length of screen _____
Type of pump Set
Capacity of pump Installed by
Depth of pump setting owner

Outside casing 8" X 24'8"

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top Soil	0 Feet	12' Ft.
Hard Blue shale	12'	21'
Same Rock	21'	23'
Blue shale	23'	26'
Glacial Drift	26'	32'
Water in glacial drift		

Above well was gravel packed
with three tons gravel between
8" and 5" casing - 5" casing
was perforated


Blue shale 32' 45'

PUMPING TEST

Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Developed capacity 750 G.P.H.
Static level—depth to water 22' ft.
Pump installed by _____

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm M. L. DietzAddress 144 1/2 S. 6th St.Jamesville, OhioDate June 3-1956Signed M. L. Dietz89-12
LOCATED

HOG