

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

N^o 119529

County Muskingum Township Falls Section of Township _____ or Lot Number _____
Owner H. R. Teisinger Address Dillon Falls Rd. Zanesville, O
Location of property Between Route 40 & Dillon Falls

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 40'
Type of screen _____ Length of screen _____
Type of pump Installed
Capacity of pump by
Depth of pump setting at herts

PUMPING TEST


Pumping rate 7 G.P.M. Duration of test 1 hrs.
Drawdown 6 ft. Date July 30-56
Developed capacity 7
Static level—depth to water 29' ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top Soil	0 Feet	9 Ft.
Sand	9'	39'
Blue Shale	39'	48'
Gray Sand Rock	48'	63'
Water in sand Rock		
at 59'		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.

See reverse side for instructions

Drilling Firm M. L. Dutro Date July 31-1956
Address 144 1/2 S. 6th St Signed M. L. Dutro
Zanesville, O

414