

WELL LOG AND DRILLING REPORT

ORIGINAL

64

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

No 124799

County Butler Township Wayne Section of Township 18
or Lot Number
Owner Wm H. Rhoten Address 5734 Wayne Milford Rd
Location of property 5734 Wayne Milford Rd. Hamilton Ohio

CONSTRUCTION DETAILS

Casing diameter 5 7/8 Length of casing 22'
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting

PUMPING TEST

Pumping rate G.P.M. Duration of test hrs.
Drawdown ft. Date
Developed capacity
Static level—depth to water 23 ft.
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>Blue clay & Stone</u>	<u>10'</u>	<u>55'</u>

water at 39'
25 gal. per hr.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
W. E.
S.
Wayne Milford Rd. 127

See reverse side for instructions

Drilling Firm Elihu Rowe
Address Seven mile Ohio

Date July 18, 1957
Signed Elihu Rowe

