

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

DEPARTMENT OF NATURAL RESOURCES

Division of Water
Columbus, Ohio

LOCATED

14

No 125208

County Holmes Township (Richland) Section of Township
or Lot NumberOwner L.G. Brown Address R 1 Brinkhaven, Ohio

Location of property

CONSTRUCTION DETAILS

Casing diameter 2 1/2" Length of casing 33' 1"
 Type of screen Length of screen
 Type of pump
 Capacity of pump
 Depth of pump setting

PUMPING TEST

Bailed Test
 Pumping rate 900 gal. per hr. Duration of test hrs.
 Drawdown None ft. Date Aug. 29, 1955
 Developed capacity 900 gal. per hr.
Couldnt bail down. Static level—depth to water 16 ft.
 Pump installed by


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
0-9 yellow clay	0 Feet	9 Ft.
hard shell	9	10
blue mud	10	27
Broken coal	27	29
Blue shale	29	33
Blue shale	33	42
Sand	42	44

At 29' water stood 14 ft in hole
 Bore down 2 ft. at 8 gal per min
 Water at 42' to 44'

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Wm F. HillAddress Box 130 Killbuck, OhioDate Sept 13, 1955Signed Wm F. Hill

14