

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

No 125582 ✓

County Madison Township N. Jackson Section of Township
or Lot Number

Owner Mr Stephens Address Gault Rd

Location of property 2 miles South East of N. Jackson on Gault Rd

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 6 1/4" Length of casing 82'
Type of screen _____ Length of screen _____
Type of pump Deming Submersible
Capacity of pump 600 gph
Depth of pump setting 100'
Pumping rate 12 G.P.M. Duration of test _____ hrs.
Drawdown Bottom ft. Date 11-29-54
Developed capacity _____
Static level—depth to water 25' ft.
Pump installed by Walsh Pump Co

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

0 Feet 5 Ft.

clay

shale

Sandy shale

Blue shale

Sandy shale

5

60'

60

72'

72

80'

80

102'

Red water at 50'

Cased off

2nd water at

95'

W.

E.

S.

See reverse side for instructions

Drilling Firm Walsh Pump Supply

Date 12-10-54

Address 426 N. G. Kellen

Signed Robert F. Walsh

190
LOCATED