

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 126014

County Licking Township Lima Section of Township
or Lot Number
Owner Ralph E. Needs Address Summit Sta. P. O.
Location of property 163 E. Broad St. Summit Sta. Ohio

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 75'
Type of screen perforated Length of screen 3'
Type of pump
Capacity of pump
Depth of pump setting

PUMPING TEST

Pumping rate.....G.P.M. Duration of test.....hrs.
Drawdown.....ft. Date 11-21-55
Developed capacity
Static level—depth to water.....29 1/2 ft.
Pump installed by owner

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow clay</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>Blue clay</u>	<u>12' to</u>	<u>73'</u>
<u>Sand & gravel</u>	<u>73'</u>	<u>75'</u>
<u>with water</u>		

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

W.

E.

N.

S.

E. Broad St
& well

See reverse side for instructions

Drilling Firm Palastola Ohio
Address Palastola Ohio

Date 11-21-55
Signed Inter N.brook