

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 141211

County Butler Township Wayne Section of Township 18
or Lot Number
Owner Willis Hamblin Address 5708 Wayne-Milford Rd.
Location of property Wayne Milford

CONSTRUCTION DETAILS

Casing diameter 6 ID Length of casing 22
Type of screen none Length of screen
Type of pump none
Capacity of pump
Depth of pump setting

PUMPING TEST

Pumping rate 120 G.P.M. Duration of test 1 hrs.
Drawdown 5 feet ft. Date 10 - 7 - 59
Developed capacity 120 G.P.M.
Static level—depth to water 15 feet ft.
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
Clay to	17	feet
shale to	20	feet
water at	28	feet
limestone to	46	feet

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
W. Wayne Milford E.
well
46
S. Trout
Milford

See reverse side for instructions

Drilling Firm

North position

Address

Ohio

Date

7 - 10 - 59

Signed

for Pipe

69
Road
Milford