

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 146324

County Montgomery Township Jefferson Section of Township 2
or Lot Number
Owner Wayne Davis Address 184 Taft Avenue Dayton 7, Ohio
Location of property 184 Taft Ave

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 6" Length of casing 57'
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting

Pumping rate G.P.M. Duration of test hrs.
Drawdown ft. Date
Developed capacity
Static level—depth to water 15' ft.
Pump installed by

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay & Gravel	0 Feet	47 Ft.
Sand, Clay & Gravel	47	50
Sand & Clay	50	53
Sand, Gravel & Water	53	57

Dip Test Approx. 15 G.P.M.
15' Draw Down

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. West Third Street E.

184 Taft Ave.

S.

See reverse side for instructions

Drilling Firm Earl Hollandsworth, Inc.
Address 872 Small Road Dayton 4, Ohio

Date September 26, 1955

Signed Malcolm V. Hollandsworth, Secy

55