# WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

**Nº 146333**

County Green Township Bath Section of Township or Lot Number Lot 40 Hamilton Platt

Owner George & Margie Bellew Address 82 Dorothy Ave. Fairborn, Ohio

Location of property 82 Dorothy Ave. Fairborn, Ohio

## CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 285 Ft.

Type of screen Length of screen

Type of pump

Capacity of pump

*Depth of pump setting*

## PUMPING TEST

Pumping rate 6 G.P.M. Duration of test 17½ hrs.

Drawdown ft. Date

Developed capacity

Static level—depth to water 100 ft.

*Pump installed by*

## WELL LOG

| Formations Sandstone, shale, limestone, *gravel and clay* | From | To |
|---|---|---|
| Fill | 0 Feet | 4 Ft. |
| Gravel | 4 | 50 |
| Sand | 50 | 80 |
| Clay & Gravel | 80 | 150 |
| Quick Sand | 150 | 250 |
| Fine Sand | 250 | 280 |
| Sand Some Gravel | 280 | 285 |

Dip test Approx 8G.P.M.

## SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.




See reverse side for instructions

Drilling Firm Earl Hollandsworth Well Drilling
Address 5872 Shull Road Dayton 24, Ohio.

Date March 26, 1960

Signed

LOCATED