

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 148003

County Clermont Township Goshen Section of Township or Lot Number ✓

Owner George Charles Krohn Address Louland R.R. 1.

Location of property Hill Station 161 + Dallasburg 51 - 3 hours South DALLASBURG RD.

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 26'
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —

PUMPING TEST


Pumping rate 8 ^{H.P.} G.P.M. Duration of test 4 hrs.
Drawdown 53' ft. Date —
Developed capacity —
Static level—depth to water 17' ft.
Pump installed by —

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>TOP SOIL</u>	<u>0 Feet</u>	<u>26 Ft.</u>
<u>Limestone</u>	<u>26'</u>	<u>70'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Home Well Drilling Co Date Nov 30/56

Address P.O. Box 421 Signed Charles Harris

Sharonville Ohio.

(2)