

WELL LOG AND DRILLING REPORT

ORIGINAL



State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

29-35

59

Nº 148241

County DELAWARE Township DELAWARE Section of Township
or Lot Number
Owner P. D. CROSSWITE Address 469 1/2 N. SUNDUSKY ST DEL. O
Location of property 1/4 mi S. of DEL. O, ON U.S. ROUTE 23

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 4" Length of casing 35'Pumping rate 10 G.P.M. Duration of test 2 hrs.

Type of screen Length of screen

Drawdown 2 ft. Date 6-11-57

Type of pump

Developed capacity 10

Capacity of pump

Static level—depth to water 24 ft.

Depth of pump setting

Pump installed by

WELL LOG


SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>CLAY</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>11 GRAVEL-SAND</u>	<u>12</u>	<u>35</u>
<u>LIMESTONE</u>	<u>35</u>	<u>57</u>

WATER AT 30'

902
35
867

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Drilling Firm NARBERT HUDSONDate 6-11-57Address OSTRANDER OHIOSigned [Signature]