

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

W35

Nº 148581

County LICKING Township GRANVILLE Section of Township or Lot Number _____
Owner P. C. QUICK Address GRANVILLE Rd-2
Location of property MI. (ON CO. Rd. 110) NORTH of ECT. STATE 37
+ CO. Rd 110. HOUSE on EAST of Rd.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 60'
Type of screen PERF. Length of screen 35'
Type of pump _____
Capacity of pump _____
Depth of pump setting _____

PUMPING TEST

Pumping rate 25 G.P.M. Duration of test 2 hrs.
Drawdown 15 ft. Date 2-14-58
Developed capacity _____
Static level—depth to water 18 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>LIGHT BROWN CLAY</u>	<u>0 Feet</u>	<u>57 Ft.</u>
<u>SAND</u>	<u>56</u>	<u>59</u>
<u>LIGHT BROWN CLAY</u>	<u>59</u>	<u>61</u>
<u>WATER</u>	<u>56'</u>	<u>59'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. ST Rd. 37

S.

See reverse side for instructions

Drilling Firm LOYD VARNER
Address HANOVER RFD #1

Date 2-14-1958
Signed Lloyd Varner



(35)