

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

No 154021

County Montgomery Township Randolph Section of Township lot 277
or Lot Number

Owner Herman Ashburn Address 313 Putz Ave Dayton Ohio

Location of property Well on Circle Dr in Irony Platt

Circle Dr 2nd East of Rt 48

Barber Test

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 5 5/8 Length of casing 36
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Pumping rate 5 G.P.M. Duration of test 1/2 hrs.
Drawdown 11 ft. Date
Developed capacity
Static level—depth to water 29 ft.
Pump installed by


WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top soil</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>Clay + gravel</u>	<u>2</u>	<u>30</u>
<u>Sand + gravel</u>	<u>30</u>	<u>36</u>
<u>Blue shale</u>	<u>36</u>	<u>90</u>

Water 36

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm CEED D Conway

Date July 9 1956

Address Rt 1 New Carlisle Ohio

Signed CEED D Conway

I