

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

7 AL-E
B.O. No 167044

County Sandusky Township Bellevue Section of Township 9
or Lot Number 9
Owner Nick Lauer Address Fremont Ohio
Location of property Fashion Hills add. of us. 53 west

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 24
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....

PUMPING TEST

Pumping rate..... G.P.M. Barley Duration of test 1 hrs.
Drawdown 10 ft. Date 5-18-56
Developed capacity 10
Static level—depth to water 29 ft.
Pump installed by.....

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

..... Ft.

Yellow Clay

0

12

Blue mud

12

20

Lime Shells

20

25

Lime

25

75

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

X

Cale Rd.

E.

S.

Water at 65
72

63413719

see 1.10 8007.

See reverse side for instructions