

## WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
Columbus, Ohio

Nº 171349

County Greene Township Bath Section of Township  
or Lot Number

Owner Cecil Rose Address Dayton Ohio

Location of property Charmont Rd 1/4 mile East  
4102 Charmont Dr

## CONSTRUCTION DETAILS

## PUMPING TEST

Casing diameter 5 5/8 Length of casing 104'  
Type of screen Length of screen  
Type of pump  
Capacity of pump  
Depth of pump setting

Pumping rate.....G.P.M. Duration of test.....hrs.  
Drawdown.....ft. Date  
Developed capacity  
Static level—depth to water.....ft.  
Pump installed by

## WELL LOG

## SKETCH SHOWING LOCATION

Formations  
Sandstone, shale, limestone,  
gravel and clay

From

To

0 Feet

15 Ft.

15

40

40

80

80

100

100

104

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.

W.

E.

N.

S.

See reverse side for instructions

Drilling Firm Robert HaysDate 3/13/57Address 525 Eda DriveSigned Robert Hays