

WELL LOG AND DRILLING REPORT

ORIGINAL

X = 2,007,000 ± 1000

Y = 206,000 ± 300

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

W6
N^o 174401

County LICKING Township BURLINGTON Section of Township
or Lot Number

Owner CHARLES MUSTON Address Ytica, Ohio

Location of property ONE MILE S.W OF Ytica

CONSTRUCTION DETAILS

PUMPING TEST


Casing diameter 4 Length of casing 34 Pumping rate 10 G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____ Drawdown _____ ft. Date _____
Type of pump _____ Developed capacity _____
Capacity of pump _____ Static level—depth to water 60 ft.
Depth of pump setting _____ Pump installed by BAILING TEST ONLY

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>CLAY</u>		<u>15</u>
<u>SHALE</u>	<u>15</u>	<u>33</u>
<u>SLATE</u>	<u>33</u>	<u>40</u>
<u>GRAY ROCK</u>	<u>40</u>	<u>60</u>
<u>SLATE</u>	<u>60</u>	<u>80</u>
<u>SAN STONE</u>	<u>80</u>	<u>90</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm R.C. BEBOUT
Address MARTINSBURG, O.

Date JUNE 27-1956
Signed R.C. BEBOUT

64