

WELL LOG AND DRILLING REPORT

#12600

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 177102

51.845

LOCATED

County Adams Township Buckeye Section of Township 12Owner Mrs Emiline Hurd Address _____Location of property 2 miles S. of Lynx O. SR125

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 5/8 Length of casing _____
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Developed capacity _____
Static level—depth to water _____ ft.
Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

4 Ft.

3

23

23

32

top soil
mud
blue limestone

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

845 S
822 TB

W.

SR 125 LYNX O.

E.

well

S.

See reverse side for instructions

Drilling Firm Dennis Hillman Date Aug 2 - 59Address Lynx O. Signed D. Hillman

12