

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

ORIGINAL
El. 802 (Hand level to
808 Bm)

No. 177126

LOCATED

County Adams Township Brush Creek Section of Township 10
Owner John R. Lathfield Address Lynch
Location of property 2 1/2 miles S. of Lynch on Lynch Rd.

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 7
Type of screen 1/8 Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST

Pumping rate.....G.P.M. Duration of test.....hrs.
Drawdown.....ft. Date.....
Developed capacity.....
Static level—depth to water.....ft.
Pump installed by.....

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

6 Ft.

top soil & clay
lime stone

6

5 3/4


Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

802 - S
796 TB

W.

E.



See reverse side for instructions

Drilling Firm Dewey Hillman

Date 11/18/58

Address Lynch O.

Signed D. Hillman

10