

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 178349

County Mahoning Township Youngstown Section of Township _____

Owner George Arhbor Address Datson Ave. Y.O.

Location of property _____

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 48'

Type of screen _____ Length of screen _____

Type of pump 1/2 hp. Jet

Capacity of pump 6 gpm

Depth of pump setting 65'

Date of completion 6-7-58

BAILING OR PUMPING TEST

Pumping rate 15 G.P.M. Duration of test 1 hrs.

Drawdown 64 ft. Date 6-7-58

Developed capacity 6 gpm

Static level—depth to water 10 ft.


Pump installed by Stewart's Pump Shop

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	48 Ft.
<u>Clay</u>	<u>48</u>	<u>74</u>
<u>Shale</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Stewart's Pump Shop

Date 6-10-58

Address 29 Hubbard Rd. Y.O.

Signed R. Stewart

10
LOCATED
10