

## WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
1500 Dublin Road  
Columbus, Ohio

No. 179211

15

County Butler Township Liberty Section of Township 14  
Owner Charles C. Mosher Address Bethany - 0  
Location of property Bethany Road - East of Route 25

## CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 26-09"  
Type of screen..... Length of screen.....  
Type of pump.....  
Capacity of pump.....  
Depth of pump setting.....  
Date of completion.....

## BAILING OR PUMPING TEST

Pumping rate..... G.P.M. Duration of test..... hrs.  
Drawdown..... ft. Date.....  
Developed capacity..... 80 G.P. Hour  
Static level—depth to water..... 10 ft.  
Pump installed by.....

## WELL LOG

## SKETCH SHOWING LOCATION

Formations  
Sandstone, shale, limestone,  
gravel and clay

From

To

Top Soil

0 Feet

3 Ft.

Yellow clay

3

12

Grey sandy clay

12

18

Blue clay

18


25

Shale

25

85

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm O. O. Pegg & CoDate Dec-20-57Address Middletown - 0Signed W. R. Payne15  
LOCATED