

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 179216

County Butler Township Liberty Section of Township 26
Owner Bernard Schenck Address 635 Princeton Rd. Hamilton, O.
Location of property St. Route 129

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 68-06
Type of screen..... Length of screen.....
Type of pump Sta Prime Jet
Capacity of pump.....
Depth of pump setting.....
Date of completion Sept 3-58

BAILING OR PUMPING TEST


Pumping rate..... G.P.M. Duration of test..... hrs.
Drawdown..... ft. Date.....
Developed capacity 10 G.P.M.
Static level—depth to water 32 ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
yellow Sandy Clay	0 Feet	19 Ft.
gray Sandy Clay	19	26
yellow Sandy Clay	26	33
gray Sandy Clay	33	36
Brown Sandy Clay	36	40
gray med sand & gravel (w.B)	40	40 1/2
Brown Sandy Clay	40 1/2	46
gray Sandy Clay	46	54
gray Sandy Clay	54	58
gray Sandy Clay	58	60
gray med sand & clay (w.B)	60	65
Shale	65	85

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm O. O. Payne & Co.
Address Middleton, O.

Date Sept. 3-58
Signed O. O. Payne

42
LOCATED