

WELL LOG AND DRILLING REPORT

ORIGINAL

46A

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 181785

County Meigs Township Salem Section of Township 5
Owner Ward Nicholson Address Chester Ohio
Location of property Chester, Ohio

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 521
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion Aug. 20 - 1960

BAILING OR PUMPING TEST


Pumping rate..... G.P.M. Duration of test..... hrs.
Drawdown..... ft. Date.....
Developed capacity.....
Static level—depth to water 47' ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow Clay</u>	0 Feet	<u>18</u> Ft.
<u>Sandstone</u>	<u>18</u>	<u>23</u>
<u>Blue Shale</u>	<u>23</u>	<u>45</u>
<u>Slate</u>	<u>45</u>	<u>51</u>
<u>Shale</u>	<u>51</u>	<u>63</u>
<u>yellow Sandstone</u>	<u>63</u>	<u>75</u>
<u>Soapstone</u>	<u>75</u>	<u>79</u>
<u>Sandstone</u>	<u>79</u>	<u>97</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Ray Stone
Address Sangerville

Date Sept. 19
Signed Ray Stone

A14