

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 181789

County Hall Township Kegonsa Section of Township Cheshire
Owner L.J. Reynolds Address C Cheshire, O
Location of property Cheshire O - 2nd house South of Traffic Light

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 72
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion Sept 30-60

BAILING OR PUMPING TEST

Pumping rate G.P.M. Duration of test hrs.
Drawdown ft. Date
Developed capacity
Static level—depth to water 32' ft.
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>CLAY</u>	0 Feet	<u>28</u> Ft.
<u>DRY GRAVEL</u>	<u>28</u>	<u>38</u>
<u>SAND AND GRAVEL</u>	<u>38</u>	<u>72</u>

Good water

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
Route 7
W. Route 554
E.
S.
Reynolds
53

See reverse side for instructions

Drilling Firm Ray Stone
Address Lancaster, Ohio

Date Oct 7-1960
Signed Ray Stone
STRT 7