

WELL LOG AND DRILLING REPORT

cor

ORIGINAL

SC 89 ✓

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 181795

County Meigs Township Julia Section of Township 12
Owner Wyatt Radford Address Rd Pomeroy
Location of property Route 33 - North of Pomeroy

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 7/8 Length of casing 37 Pumping rate.....G.P.M. Duration of test.....hrs.
Type of screen..... Length of screen..... Drawdown.....ft. Date.....
Type of pump..... Developed capacity.....
Capacity of pump..... Static level—depth to water 30 ft.
Depth of pump setting..... Pump installed by.....
Date of completion.....

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet 9 Ft.

CLAY

9 24

RED CLAY

24 40

GRAY SANDSTONE

40 45

LIME

45 55

GRAY SAND

55 80

BLUE SANDSTONE

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Athens
State Route 33
Radford
Rocksprings
W. E.

1.14 mi. N of center
back to

S.

See reverse side for instructions

Drilling Firm Ray Stone

Date May 28, 1961

Address Londonville, O

Signed Ray Stone