

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 182387

County Wood Township Montgomery Section of Township _____
Owner Thomas Cullison Address Rising Sun, Ohio
Location of property North Vine St.

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 40'9"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date 6/27/62
Developed capacity _____
Static level—depth to water _____ ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Sand</u>	<u>0 Feet</u>	<u>5 Ft.</u>
<u>Limestone</u>	<u>5</u>	<u>51</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm H. J. Gschwind
Address Rising Sun, O

Date 6/27/62
Signed H. J. Gschwind